



www.minelab.com


WM 09

WIRELESS AUDIO MODULE


EN Getting Started Guide




CONNECT WATERPROOF HEADPHONES




CONNECT STANDARD HEADPHONES




TURN ON




PAIR TO DETECTOR (FIRST-USE)




TURN OFF




RECONNECT TO PREVIOUSLY PAIRED DETECTOR



PAIRING TIMEOUT



PAIR TO DIFFERENT DETECTOR (AFTER FIRST-USE)




LOW BATTERY

Bateria baja
Niedriger akkustand
Pile faible
Niski poziom naładowania baterii



CHARGING

Cargando
Aufladen
Chargement
Ładowanie



CARE AND MAINTENANCE – WM 09 WIRELESS AUDIO MODULE

- Keep the Headphone Socket clean and dry. Always replace the Dust Cap when not in use.
- The WM 09 is only waterproof when Minelab waterproof headphones are connected to the Headphone Socket.
- Do not connect any headphones if the Headphone Socket is damp or wet.
- Before charging, make sure the Magnetic Charging Connector is clean, dry and free of debris and salt residue.
- Do not clean the Magnetic Charging Connector with abrasives or chemicals.
- If the Magnetic Charging Connector contacts are corroded, gently clean with a soft pencil eraser.
- Do not clean the WM 09 with chemicals – wipe with a damp cloth or use soapy water if needed.
- The WM 09 contains an internal lithium battery – only dispose of the product in accordance with local regulations.
- Do not charge the battery in temperatures outside of the charging temperature range (0°C to 40°C/ 32°F to 104°F).



lmsmetaldetecting.com